

**RACING MEMO**

**DATE:** August 5, 2015

**NUMBER:** RM 15-08

**FROM:** Club Racing Board

**TO:** All Members

**SUBJECT:** Spec Miata Camshaft Sensor Connection

Effective immediately, in 9.1.7.C.1.p, add a new section 9 as follows:

*"An electrical pigtail ranging from 3" to 6" in length and terminated with any 3 pin electrical connector may be soldered and potted to the OEM cam sensor for the purpose of correcting a known issue with the factory connection. The factory harness connector may be removed and replaced with the appropriate mating connector."*